







Steps to enable Citroen/Peugeot CD changer port with Proxia diagnostic tool:



Steps to enable Citroen/Peugeot CD changer port with Lexia diagnostic tool:

